

This image shows a single sheet of white paper with horizontal ruling lines. The lines are evenly spaced and run across the width of the page. There are no margins, text, or other markings on the paper.

This image shows a single sheet of white paper with horizontal ruling lines. The lines are evenly spaced and run across the width of the page. There are no margins, text, or other markings on the paper.

This image shows a single sheet of white paper with horizontal ruling lines. The lines are evenly spaced and run across the width of the page. There are no margins, text, or other markings on the paper.

[illegible]



**River Forest Fire Department**  
**400 Park Avenue**  
**River Forest, IL 60305**  
**Phone: (708) 366-7629**

## Fire and Life Safety Inspection Report

**Inspection Status**

Completed

**Inspected by**

Wiley, Kevin

**Completed at**

09/19/2025 11:27:24

<b>Business Name:</b> Dominican University---Coughlin Hall	<b>Date/Time of Inspection:</b> 09/19/2025 11:27:24
<b>Address:</b> 7900 DIVISION ST, RIVER FOREST, IL, 60305	<b>Inspected by:</b> Wiley, Kevin
<b>Suite/Unit:</b> --	<b>Inspection Status:</b> <u>Completed</u>
<b>Inspection Number:</b> RFFI-2025-0000035-1	

### EXPLANATION OF PERIODIC FIRE INSPECTION REPORT AND YOUR RESPONSIBILITIES AS BUSINESS OWNER, MANAGER OR DESIGNATED REPRESENTATIVE ORDER TO COMPLY:

Village Ordinances and General Statutes charge the Fire Code Official with the responsibility of protecting the people and properties from the ravages of fire. This is accomplished by an organized program of inspections, and enforcement of Codes, Statutes, and Standards intended to minimize the community's fire loss. If there are any questions or needs for assistance with the correction of the violations, don't hesitate to contact The River Forest Fire Department Fire Marshals Office at 708-714-3562 | kwiley@vrf.us.

### ELECTRICAL CONTROL PANEL:

✓ Resolved

**ITEM:** EMERGENCY LIGHTS-Working

### REMARK:

Service the Emergency Lights system.

1. 2nd floor North, Men's bathroom, 2 lights.
2. 2nd floor North, Women's bathroom 1 light.

**ITEM:** EXIT LIGHTS-Working

**REMARK:**

1. Wellness Center, 1 EM/Exit light by main Exit Door.
2. The older unit above the rear exit stairs may be removed as there are 3 lights within 6 feet. If it remains, It must be operational and work when tested.

Next inspection scheduled to be conducted on or after 08/14/2026

## Inspection Signatures

### Occupancy Contact Signature

Unable to sign:

Jonathan handled the reinspection

---

Sasha Santiago  
Security Contact  
708-524-6750  
ssantiago@dom.edu  
7900 Division St.

### Inspector Signature



---

Wiley, Kevin  
--  
Fire Marshal  
630-270-6988  
kwiley@vrf.us



**River Forest Fire Department**  
**400 Park Avenue**  
**River Forest, IL 60305**  
**Phone: (708) 366-7629**

## Fire and Life Safety Inspection Report

**Inspection Status**  
Completed with violation

**Inspected by**  
Wiley, Kevin

**Completed at**  
08/14/2025 10:00:00

<b>Business Name:</b> Dominican University---Coughlin Hall	<b>Date/Time of Inspection:</b> 08/14/2025 10:00:00
<b>Address:</b> 7900 DIVISION ST, RIVER FOREST, IL, 60305	<b>Inspected by:</b> Wiley, Kevin
<b>Suite/Unit:</b> --	<b>Inspection Status:</b> <u>Completed with violation</u>
<b>Inspection Number:</b> RFFI-2025-0000035	

### EXPLANATION OF PERIODIC FIRE INSPECTION REPORT AND YOUR RESPONSIBILITIES AS BUSINESS OWNER, MANAGER OR DESIGNATED REPRESENTATIVE ORDER TO COMPLY:

Village Ordinances and General Statutes charge the Fire Code Official with the responsibility of protecting the people and properties from the ravages of fire. This is accomplished by an organized program of inspections, and enforcement of Codes, Statutes, and Standards intended to minimize the community's fire loss. If there are any questions or needs for assistance with the correction of the violations, don't hesitate to contact The River Forest Fire Department Fire Marshals Office at 708-714-3562 | kwiley@vrf.us.

### ELECTRICAL CONTROL PANEL:

#### ✖ Violation

**ITEM:** EMERGENCY LIGHTS-Working

### REMARK:

Service the Emergency Lights system.

1. 2nd floor North, Men's bathroom, 2 lights.
2. 2nd floor North, Women's bathroom 1 light.

## **✕ Violation**

**ITEM:** EXIT LIGHTS-Working

---

**REMARK:**

1. Wellness Center, 1 EM/Exit light by main Exit Door.
  2. The older unit above the rear exit stairs may be removed as there are 3 lights within 6 feet. If it remains, It must be operational and work when tested.
- 

Re-Inspection scheduled to be conducted on or after 09/04/2025 at 09:30  
Next inspection scheduled to be conducted on or after 08/14/2026

## **Inspection Signatures**

### **Occupancy Contact Signature**

**Unable to sign:**

**Report was finished in Office.**

---

Sasha Santiago  
Security Contact  
708-524-6750  
ssantiago@dom.edu  
7900 Division St.

### **Inspector Signature**



---

Wiley, Kevin  
--  
Fire Marshal  
630-270-6988  
kwiley@vrf.us





**River Forest Fire Department**  
**400 Park Avenue**  
**River Forest, IL 60305**  
**Phone: (708) 366-7629**

## Fire and Life Safety Inspection Report

**Inspection Status**  
Completed with violation

**Inspected by**  
Wiley, Kevin

**Completed at**  
09/19/2025 12:46:55

<b>Business Name:</b> Dominican University---Fine Arts Building	<b>Date/Time of Inspection:</b> 09/19/2025 12:46:55
<b>Address:</b> 7900 DIVISION ST, RIVER FOREST, IL, 60305	<b>Inspected by:</b> Wiley, Kevin
<b>Suite/Unit:</b> --	<b>Inspection Status:</b> <u>Completed with violation</u>
<b>Inspection Number:</b> RFFI-2025-0000034-1	

### EXPLANATION OF PERIODIC FIRE INSPECTION REPORT AND YOUR RESPONSIBILITIES AS BUSINESS OWNER, MANAGER OR DESIGNATED REPRESENTATIVE ORDER TO COMPLY:

Village Ordinances and General Statutes charge the Fire Code Official with the responsibility of protecting the people and properties from the ravages of fire. This is accomplished by an organized program of inspections, and enforcement of Codes, Statutes, and Standards intended to minimize the community's fire loss. If there are any questions or needs for assistance with the correction of the violations, don't hesitate to contact The River Forest Fire Department Fire Marshals Office at 708-714-3562 | kwiley@vrf.us.

### INSIDE EXITWAYS:

#### ✖ Violation

**ITEM:** FIRE DOORS-Operation

### REMARK:

The Rolling Fire Door separating the stage from the Scene Shop does indeed need to be operational with fusible links controlling it.

### ELECTRICAL CONTROL PANEL:

#### ✔ Resolved

**ITEM:** EXTENSION CORDS-Use

**REMARK:**

1. Remove the orange extension cord running under the rug. Rear of Martin Recital Hall Audience.
2. Fashion Lab - Discontinue the use of the Non-Protected, without overcurrent protected, "tower of power" by the far wall.
3. Discontinue the use of a lamp-cord style Brown extension cord as permanent wiring off of that same tower of power.

---

✓ Resolved

**ITEM:** EMERGENCY LIGHTS-Working

**REMARK:**

Service the Emergency Lights. By the West Stairs , 1st floor in hallway.

---

✓ Resolved

**ITEM:** EXIT LIGHTS-Working

**REMARK:**

Service the Exit Lights

- 1st floor North-Center stairs

---

Re-Inspection scheduled to be conducted on or after 10/03/2025 at 09:00

# Inspection Signatures

## Occupancy Contact Signature

Unable to sign:

Jonathan did the Reinspection

---

Sasha Santiago  
Security Contact  
708-524-6750  
ssantiago@dom.edu  
7900 Division

## Inspector Signature



---

Wiley, Kevin

--

Fire Marshal  
630-270-6988  
kwiley@vrf.us



**River Forest Fire Department**  
**400 Park Avenue**  
**River Forest, IL 60305**  
**Phone: (708) 366-7629**

## Fire and Life Safety Inspection Report

**Inspection Status**  
Completed with violation

**Inspected by**  
Wiley, Kevin

**Completed at**  
08/14/2025 09:30:00

<b>Business Name:</b> Dominican University---Fine Arts Building	<b>Date/Time of Inspection:</b> 08/14/2025 09:30:00
<b>Address:</b> 7900 DIVISION ST, RIVER FOREST, IL, 60305	<b>Inspected by:</b> Wiley, Kevin
<b>Suite/Unit:</b> --	<b>Inspection Status:</b> <u>Completed with violation</u>
<b>Inspection Number:</b> RFFI-2025-0000034	

### EXPLANATION OF PERIODIC FIRE INSPECTION REPORT AND YOUR RESPONSIBILITIES AS BUSINESS OWNER, MANAGER OR DESIGNATED REPRESENTATIVE ORDER TO COMPLY:

Village Ordinances and General Statutes charge the Fire Code Official with the responsibility of protecting the people and properties from the ravages of fire. This is accomplished by an organized program of inspections, and enforcement of Codes, Statutes, and Standards intended to minimize the community's fire loss. If there are any questions or needs for assistance with the correction of the violations, don't hesitate to contact The River Forest Fire Department Fire Marshals Office at 708-714-3562 | kwiley@vrf.us.

### INSIDE EXITWAYS:

#### ✖ Violation

**ITEM:** FIRE DOORS-Operation

### REMARK:

The Rolling Fire Door separating the stage from the Scene Shop does indeed need to be operational with fusible links controlling it.

### ELECTRICAL CONTROL PANEL:

#### ✖ Violation

**ITEM:** EXTENSION CORDS-Use

**REMARK:**

1. Remove the orange extension cord running under the rug. Rear of Martin Recital Hall Audience.
2. Fashion Lab - Discontinue the use of the Non-Protected, without overcurrent protected, "tower of power" by the far wall.
3. Discontinue the use of a lamp-cord style Brown extension cord as permanent wiring off of that same tower of power.

---

**✕ Violation****ITEM:** EMERGENCY LIGHTS-Working**REMARK:**

Service the Emergency Lights. By the West Stairs , 1st floor in hallway.

---

**✕ Violation****ITEM:** EXIT LIGHTS-Working**REMARK:**

Service the Exit Lights

- 1st floor North-Center stairs

---

Re-Inspection scheduled to be conducted on or after 09/04/2025 at 09:00

Next inspection scheduled to be conducted on or after 08/14/2026

# Inspection Signatures

## Occupancy Contact Signature

Unable to sign:

Report was finished in office

---

Sasha Santiago  
Security Contact  
708-524-6750  
ssantiago@dom.edu  
7900 Division

## Inspector Signature



---

Wiley, Kevin  
--  
Fire Marshal  
630-270-6988  
kwiley@vrf.us



**River Forest Fire Department**  
**400 Park Avenue**  
**River Forest, IL 60305**  
**Phone: (708) 366-7629**

## Fire and Life Safety Inspection Report

**Inspection Status**

Completed

**Inspected by**

Wiley, Kevin

**Completed at**

08/11/2025 11:00:00

<b>Business Name:</b> Dominican University---Igini Gymnasium	<b>Date/Time of Inspection:</b> 08/11/2025 11:00:00
<b>Address:</b> 7900 DIVISION ST, RIVER FOREST, IL, 60305	<b>Inspected by:</b> Wiley, Kevin
<b>Suite/Unit:</b> --	<b>Inspection Status:</b> <u>Completed</u>
<b>Inspection Number:</b> RFFI-2025-0000032	

### EXPLANATION OF PERIODIC FIRE INSPECTION REPORT AND YOUR RESPONSIBILITIES AS BUSINESS OWNER, MANAGER OR DESIGNATED REPRESENTATIVE ORDER TO COMPLY:

Village Ordinances and General Statutes charge the Fire Code Official with the responsibility of protecting the people and properties from the ravages of fire. This is accomplished by an organized program of inspections, and enforcement of Codes, Statutes, and Standards intended to minimize the community's fire loss. If there are any questions or needs for assistance with the correction of the violations, don't hesitate to contact The River Forest Fire Department Fire Marshals Office at 708-714-3562 | kwiley@vrf.us.

Next inspection scheduled to be conducted on or after 08/11/2026

### Inspection Signatures

**Occupancy Contact Signature**

Unable to sign:

Report was completed in office

---

Sasha Santiago  
Security Contact  
708-524-6750

**Inspector Signature**

---

Wiley, Kevin  
--  
Fire Marshal

ssantiago@dom.edu  
7900 Division

630-270-6988  
kwiley@vrf.us





**River Forest Fire Department**  
**400 Park Avenue**  
**River Forest, IL 60305**  
**Phone: (708) 366-7629**

## Fire and Life Safety Inspection Report

**Inspection Status**

Completed

**Inspected by**

Wiley, Kevin

**Completed at**

09/19/2025 11:21:55

<b>Business Name:</b> Dominican University---Mazzuchelli Hall	<b>Date/Time of Inspection:</b> 09/19/2025 11:21:55
<b>Address:</b> 7900 DIVISION ST, RIVER FOREST, IL, 60305	<b>Inspected by:</b> Wiley, Kevin
<b>Suite/Unit:</b> --	<b>Inspection Status:</b> <u>Completed</u>
<b>Inspection Number:</b> RFFI-2025-0000037-1	

### EXPLANATION OF PERIODIC FIRE INSPECTION REPORT AND YOUR RESPONSIBILITIES AS BUSINESS OWNER, MANAGER OR DESIGNATED REPRESENTATIVE ORDER TO COMPLY:

Village Ordinances and General Statutes charge the Fire Code Official with the responsibility of protecting the people and properties from the ravages of fire. This is accomplished by an organized program of inspections, and enforcement of Codes, Statutes, and Standards intended to minimize the community's fire loss. If there are any questions or needs for assistance with the correction of the violations, don't hesitate to contact The River Forest Fire Department Fire Marshals Office at 708-714-3562 | kwiley@vrf.us.

### ELECTRICAL CONTROL PANEL:

✓ Resolved

**ITEM:** EMERGENCY LIGHTS-Working

### REMARK:

Dining Hall

### SPRINK. & STANDPIPE RISERS:

✓ Resolved

**ITEM:** Accessible

**REMARK:**

Remove Cart from the from front of the Standpipe Connection in rear kitchen hall. Done on site

---

Next inspection scheduled to be conducted on or after 08/14/2026

## Inspection Signatures


**Occupancy Contact Signature**

**Unable to sign:**

**Jonathan did the Reinspection**

---

Sasha Santiago  
Security Contact  
708-524-6750  
ssantiago@dom.edu  
7900 Division St.

**Inspector Signature**

---

Wiley, Kevin  
--  
Fire Marshal  
630-270-6988  
kwiley@vrf.us



**River Forest Fire Department**  
**400 Park Avenue**  
**River Forest, IL 60305**  
**Phone: (708) 366-7629**

## Fire and Life Safety Inspection Report

**Inspection Status**  
Completed with violation

**Inspected by**  
Wiley, Kevin

**Completed at**  
08/14/2025 11:30:00

<b>Business Name:</b> Dominican University---Mazzuchelli Hall	<b>Date/Time of Inspection:</b> 08/14/2025 11:30:00
<b>Address:</b> 7900 DIVISION ST, RIVER FOREST, IL, 60305	<b>Inspected by:</b> Wiley, Kevin
<b>Suite/Unit:</b> --	<b>Inspection Status:</b> <u>Completed with violation</u>
<b>Inspection Number:</b> RFFI-2025-0000037	

### EXPLANATION OF PERIODIC FIRE INSPECTION REPORT AND YOUR RESPONSIBILITIES AS BUSINESS OWNER, MANAGER OR DESIGNATED REPRESENTATIVE ORDER TO COMPLY:

Village Ordinances and General Statutes charge the Fire Code Official with the responsibility of protecting the people and properties from the ravages of fire. This is accomplished by an organized program of inspections, and enforcement of Codes, Statutes, and Standards intended to minimize the community's fire loss. If there are any questions or needs for assistance with the correction of the violations, don't hesitate to contact The River Forest Fire Department Fire Marshals Office at 708-714-3562 | kwiley@vrf.us.

### ELECTRICAL CONTROL PANEL:

**✗ Violation**

**ITEM:** EMERGENCY LIGHTS-Working

### REMARK:

Dining Hall

### SPRINK. & STANDPIPE RISERS:

**✓ Corrected on site**

**ITEM:** Accessible

**REMARK:**

Remove Cart from the from front of the Standpipe Connection in rear kitchen hall. Done on site

---

Re-Inspection scheduled to be conducted on or after 09/04/2025 at 11:00

Next inspection scheduled to be conducted on or after 08/14/2026

## Inspection Signatures

**Occupancy Contact Signature**

**Unable to sign:**

**Report finished in office**

---

Sasha Santiago  
Security Contact  
708-524-6750  
ssantiago@dom.edu  
7900 Division St.

**Inspector Signature**

---

Wiley, Kevin  
--  
Fire Marshal  
630-270-6988  
kwiley@vrf.us



**River Forest Fire Department**  
**400 Park Avenue**  
**River Forest, IL 60305**  
**Phone: (708) 366-7629**

## Fire and Life Safety Inspection Report

**Inspection Status**  
Completed with violation

**Inspected by**  
Wiley, Kevin

**Completed at**  
08/14/2025 11:00:00

<b>Business Name:</b> Dominican University – Murray Hall	<b>Date/Time of Inspection:</b> 08/14/2025 11:00:00
<b>Address:</b> 7900 DIVISION ST, RIVER FOREST, IL, 60305	<b>Inspected by:</b> Wiley, Kevin
<b>Suite/Unit:</b> --	<b>Inspection Status:</b> <u>Completed with violation</u>
<b>Inspection Number:</b> RFFI-2025-0000036	

### EXPLANATION OF PERIODIC FIRE INSPECTION REPORT AND YOUR RESPONSIBILITIES AS BUSINESS OWNER, MANAGER OR DESIGNATED REPRESENTATIVE ORDER TO COMPLY:

Village Ordinances and General Statutes charge the Fire Code Official with the responsibility of protecting the people and properties from the ravages of fire. This is accomplished by an organized program of inspections, and enforcement of Codes, Statutes, and Standards intended to minimize the community's fire loss. If there are any questions or needs for assistance with the correction of the violations, don't hesitate to contact The River Forest Fire Department Fire Marshals Office at 708-714-3562 | [kwiley@vrf.us](mailto:kwiley@vrf.us).

### INSIDE EXITWAYS:

#### ✖ Violation

**ITEM:** FIRE DOORS-Operation

### REMARK:

1. The Fire Door to Trash Room 409A does not close and latch. Looks to be out of adjustment at the hinges.
2. The Fire Door to Trash Room 309 catches on the carpeting and will not allow the door to open fully nor close properly.
3. The 1st floor West Stair door does not latch properly.

## ELECTRICAL CONTROL PANEL:

**✖ Violation**

**ITEM:** EMERGENCY LIGHTS-Working

### REMARK:

Service EM light on the 3rd floor, center hall

**✖ Violation**

**ITEM:** EXIT LIGHTS-Working

### REMARK:

Service the Exit Lights system in the West Stairs, exit light for the ground level exit.

## SPRINK. & STANDPIPE RISERS:

**✖ Violation**

**ITEM:** Condition

### REMARK:

The Sprinklers/Standpipe in the West Stairs on 1, 2, 3, and 4th floors are in need of Inspection/service. Last date on Current tag is from 2023.

Re-Inspection scheduled to be conducted on or after 09/04/2025 at 10:30

Next inspection scheduled to be conducted on or after 08/14/2026

## Inspection Signatures

### Occupancy Contact Signature

**Unable to sign:**

**Report was completed in office**

Sasha Santiago  
Security Contact  
(708) 524-6750

### Inspector Signature



Wiley, Kevin  
--  
Fire Marshal

ssantiago@dom.edu  
7900 Division St.

630-270-6988  
kwiley@vrf.us



**River Forest Fire Department**  
**400 Park Avenue**  
**River Forest, IL 60305**  
**Phone: (708) 366-7629**

## Fire and Life Safety Inspection Report

**Inspection Status**  
Completed with violation

**Inspected by**  
Wiley, Kevin

**Completed at**  
09/19/2025 11:14:11

<b>Business Name:</b> Dominican University – Murray Hall	<b>Date/Time of Inspection:</b> 09/19/2025 11:14:11
<b>Address:</b> 7900 DIVISION ST, RIVER FOREST, IL, 60305	<b>Inspected by:</b> Wiley, Kevin
<b>Suite/Unit:</b> --	<b>Inspection Status:</b> <u>Completed with violation</u>
<b>Inspection Number:</b> RFFI-2025-0000036-1	

### EXPLANATION OF PERIODIC FIRE INSPECTION REPORT AND YOUR RESPONSIBILITIES AS BUSINESS OWNER, MANAGER OR DESIGNATED REPRESENTATIVE ORDER TO COMPLY:

Village Ordinances and General Statutes charge the Fire Code Official with the responsibility of protecting the people and properties from the ravages of fire. This is accomplished by an organized program of inspections, and enforcement of Codes, Statutes, and Standards intended to minimize the community's fire loss. If there are any questions or needs for assistance with the correction of the violations, don't hesitate to contact The River Forest Fire Department Fire Marshals Office at 708-714-3562 | kwiley@vrf.us.

### INSIDE EXITWAYS:

✓ Resolved

**ITEM:** FIRE DOORS-Operation

### REMARK:

1. The Fire Door to Trash Room 409A does not close and latch. Looks to be out of adjustment at the hinges.
2. The Fire Door to Trash Room 309 catches on the carpeting and will not allow the door to open fully nor close properly.
3. The 1st floor West Stair door does not latch properly.



## ELECTRICAL CONTROL PANEL:

✓ Resolved

ITEM: EMERGENCY LIGHTS-Working

### REMARK:

Service EM light on the 3rd floor, center hall

✓ Resolved

ITEM: EXIT LIGHTS-Working

### REMARK:

Service the Exit Lights system in the West Stairs, exit light for the ground level exit.

## SPRINK. & STANDPIPE RISERS:

✗ Violation

ITEM: Condition

### REMARK:

The Sprinklers/Standpipe in the West Stairs on 1, 2, 3, and 4th floors are in need of Inspection/service. Last date on Current tag is from 2023.

Re-Inspection scheduled to be conducted on or after 10/10/2025 at 10:30

## Inspection Signatures


### Occupancy Contact Signature

Unable to sign:

Jonathan reviewed the violations during the re-inspection

Sasha Santiago  
Security Contact  
(708) 524-6750  
ssantiago@dom.edu  
7900 Division St.

### Inspector Signature



Wiley, Kevin  
--  
Fire Marshal  
630-270-6988  
kwiley@vrf.us





**River Forest Fire Department**  
**400 Park Avenue**  
**River Forest, IL 60305**  
**Phone: (708) 366-7629**

## Fire and Life Safety Inspection Report

**Inspection Status**  
Completed with violation

**Inspected by**  
Wiley, Kevin

**Completed at**  
09/19/2025 12:52:43

<b>Business Name:</b> Dominican University---Parking Garage	<b>Date/Time of Inspection:</b> 09/19/2025 12:52:43
<b>Address:</b> 7900 DIVISION ST, RIVER FOREST, IL, 60305	<b>Inspected by:</b> Wiley, Kevin
<b>Suite/Unit:</b> --	<b>Inspection Status:</b> <u>Completed with violation</u>
<b>Inspection Number:</b> RFFI-2025-0000031-1	

### EXPLANATION OF PERIODIC FIRE INSPECTION REPORT AND YOUR RESPONSIBILITIES AS BUSINESS OWNER, MANAGER OR DESIGNATED REPRESENTATIVE ORDER TO COMPLY:

Village Ordinances and General Statutes charge the Fire Code Official with the responsibility of protecting the people and properties from the ravages of fire. This is accomplished by an organized program of inspections, and enforcement of Codes, Statutes, and Standards intended to minimize the community's fire loss. If there are any questions or needs for assistance with the correction of the violations, don't hesitate to contact The River Forest Fire Department Fire Marshals Office at 708-714-3562 | kwiley@vrf.us.

### COMPRESSED GAS:

✓ Resolved

ITEM: Chained

### REMARK:

Secure the Oxygen tank in the workshop area from knocking over.

### Ad-hoc violations:

✗ Violation

ITEM: Please provide inspection/Operation maintenance of the Carbon Monoxide system in the garage (North walls on each level).

Re-Inspection scheduled to be conducted on or after 10/10/2025 at 10:00

## Inspection Signatures

### Occupancy Contact Signature

Unable to sign:

Jonathan did the Reinspection

---

Sasha Santiago  
Security Contact  
(708) 524-6750  
ssantiago@dom.edu  
7900 Division

### Inspector Signature



---

Wiley, Kevin  
--  
Fire Marshal  
630-270-6988  
kwiley@vrf.us



**River Forest Fire Department**  
**400 Park Avenue**  
**River Forest, IL 60305**  
**Phone: (708) 366-7629**

## Fire and Life Safety Inspection Report

**Inspection Status**  
Completed with violation

**Inspected by**  
Wiley, Kevin

**Completed at**  
08/11/2025 10:30:00

<b>Business Name:</b> Dominican University---Parking Garage	<b>Date/Time of Inspection:</b> 08/11/2025 10:30:00
<b>Address:</b> 7900 DIVISION ST, RIVER FOREST, IL, 60305	<b>Inspected by:</b> Wiley, Kevin
<b>Suite/Unit:</b> --	<b>Inspection Status:</b> <u>Completed with violation</u>
<b>Inspection Number:</b> RFFI-2025-0000031	

### EXPLANATION OF PERIODIC FIRE INSPECTION REPORT AND YOUR RESPONSIBILITIES AS BUSINESS OWNER, MANAGER OR DESIGNATED REPRESENTATIVE ORDER TO COMPLY:

Village Ordinances and General Statutes charge the Fire Code Official with the responsibility of protecting the people and properties from the ravages of fire. This is accomplished by an organized program of inspections, and enforcement of Codes, Statutes, and Standards intended to minimize the community's fire loss. If there are any questions or needs for assistance with the correction of the violations, don't hesitate to contact The River Forest Fire Department Fire Marshals Office at 708-714-3562 | kwiley@vrf.us.

### COMPRESSED GAS:

#### ✖ Violation

**ITEM:** Chained

### REMARK:

Secure the Oxygen tank in the workshop area from knocking over.

### Ad-hoc violations:

#### ✖ Violation

**ITEM:** Please provide inspection/Operation maintenance of the Carbon Monoxide system in the garage (North walls on each level).

Re-Inspection scheduled to be conducted on or after 09/01/2025 at 10:00  
Next inspection scheduled to be conducted on or after 08/11/2026

## Inspection Signatures

### Occupancy Contact Signature

Unable to sign:

Report completed in office

---

Sasha Santiago  
Security Contact  
(708) 524-6750  
ssantiago@dom.edu  
7900 Division

### Inspector Signature



---

Wiley, Kevin  
--  
Fire Marshal  
630-270-6988  
kwiley@vrf.us



**River Forest Fire Department**  
**400 Park Avenue**  
**River Forest, IL 60305**  
**Phone: (708) 366-7629**

## Fire and Life Safety Inspection Report

**Inspection Status**

Completed

**Inspected by**

Wiley, Kevin

**Completed at**

08/11/2025 11:30:00

<b>Business Name:</b> Dominican University---Parmer Academic Hall (Kitchens on 1st fl)	<b>Date/Time of Inspection:</b> 08/11/2025 11:30:00
<b>Address:</b> 7900 DIVISION ST, RIVER FOREST, IL, 60305	<b>Inspected by:</b> Wiley, Kevin
<b>Suite/Unit:</b> --	<b>Inspection Status:</b> <u>Completed</u>
<b>Inspection Number:</b> RFFI-2025-0000033	

### EXPLANATION OF PERIODIC FIRE INSPECTION REPORT AND YOUR RESPONSIBILITIES AS BUSINESS OWNER, MANAGER OR DESIGNATED REPRESENTATIVE ORDER TO COMPLY:

Village Ordinances and General Statutes charge the Fire Code Official with the responsibility of protecting the people and properties from the ravages of fire. This is accomplished by an organized program of inspections, and enforcement of Codes, Statutes, and Standards intended to minimize the community's fire loss. If there are any questions or needs for assistance with the correction of the violations, don't hesitate to contact The River Forest Fire Department Fire Marshals Office at 708-714-3562 | kwiley@vrf.us.

Next inspection scheduled to be conducted on or after 08/12/2026

## Inspection Signatures

**Occupancy Contact Signature**

Unable to sign:

Report was completed in office

---

Sasha Santiago  
Security Contact  
708-524-6750

**Inspector Signature**

---

Wiley, Kevin  
--  
Fire Marshal

ssantiago@dom.edu  
7900 Division St.

630-270-6988  
kwiley@vrf.us





**River Forest Fire Department**  
**400 Park Avenue**  
**River Forest, IL 60305**  
**Phone: (708) 366-7629**

## Fire and Life Safety Inspection Report

**Inspection Status**

Completed

**Inspected by**

Wiley, Kevin

**Completed at**

09/19/2025 11:25:05

<b>Business Name:</b> Dominican University---Power Hall	<b>Date/Time of Inspection:</b> 09/19/2025 11:25:05
<b>Address:</b> 7900 DIVISION ST, RIVER FOREST, IL, 60305	<b>Inspected by:</b> Wiley, Kevin
<b>Suite/Unit:</b> --	<b>Inspection Status:</b> <u>Completed</u>
<b>Inspection Number:</b> RFFI-2025-0000054-1	

### EXPLANATION OF PERIODIC FIRE INSPECTION REPORT AND YOUR RESPONSIBILITIES AS BUSINESS OWNER, MANAGER OR DESIGNATED REPRESENTATIVE ORDER TO COMPLY:

Village Ordinances and General Statutes charge the Fire Code Official with the responsibility of protecting the people and properties from the ravages of fire. This is accomplished by an organized program of inspections, and enforcement of Codes, Statutes, and Standards intended to minimize the community's fire loss. If there are any questions or needs for assistance with the correction of the violations, don't hesitate to contact The River Forest Fire Department Fire Marshals Office at 708-714-3562 | kwiley@vrf.us.

### INSIDE EXITWAYS:

✓ Resolved

**ITEM:** Obstructed

### REMARK:

Remove the large table from the egress path in the Underground

✓ Resolved

**ITEM:** FIRE DOORS-Operation

### REMARK:

The south Fire Door to the South Stairway on the 2nd floor does not close and latch properly.

## ELECTRICAL CONTROL PANEL:

✓ Resolved

**ITEM:** EMERGENCY LIGHTS-Working

### REMARK:

Service the following Emergency Lights:

- 4th Floor, Elevator Lobby
- Outside Room 449
- New bathroom on 1st floor. Test button cannot be found (It may be mounted too high to the ceiling to get to the test button). If that's the case, flip the box so the test button is accessible.

Next inspection scheduled to be conducted on or after 08/19/2026

## Inspection Signatures

### Occupancy Contact Signature

Unable to sign:

Jonathan did the Reinspection

---

Sasha Santiago  
Security Contact  
708-524-6750  
ssantiago@dom.edu  
7900 Division St.

### Inspector Signature



---

Wiley, Kevin  
--  
Fire Marshal  
630-270-6988  
kwiley@vrf.us



**River Forest Fire Department**  
**400 Park Avenue**  
**River Forest, IL 60305**  
**Phone: (708) 366-7629**

## Fire and Life Safety Inspection Report

**Inspection Status**  
Completed with violation

**Inspected by**  
Wiley, Kevin

**Completed at**  
08/19/2025 10:00:00

<b>Business Name:</b> Dominican University---Power Hall	<b>Date/Time of Inspection:</b> 08/19/2025 10:00:00
<b>Address:</b> 7900 DIVISION ST, RIVER FOREST, IL, 60305	<b>Inspected by:</b> Wiley, Kevin
<b>Suite/Unit:</b> --	<b>Inspection Status:</b> <u>Completed with violation</u>
<b>Inspection Number:</b> RFFI-2025-0000054	

### EXPLANATION OF PERIODIC FIRE INSPECTION REPORT AND YOUR RESPONSIBILITIES AS BUSINESS OWNER, MANAGER OR DESIGNATED REPRESENTATIVE ORDER TO COMPLY:

Village Ordinances and General Statutes charge the Fire Code Official with the responsibility of protecting the people and properties from the ravages of fire. This is accomplished by an organized program of inspections, and enforcement of Codes, Statutes, and Standards intended to minimize the community's fire loss. If there are any questions or needs for assistance with the correction of the violations, don't hesitate to contact The River Forest Fire Department Fire Marshals Office at 708-714-3562 | kwiley@vrf.us.

#### INSIDE EXITWAYS:

##### **X Violation**

**ITEM:** Obstructed

#### **REMARK:**

Remove the large table from the egress path in the Underground

##### **X Violation**

**ITEM:** FIRE DOORS-Operation

#### **REMARK:**

The south Fire Door to the South Stairway on the 2nd floor does not close and latch properly.

## ELECTRICAL CONTROL PANEL:

**X Violation**

**ITEM:** EMERGENCY LIGHTS-Working

### REMARK:

Service the following Emergency Lights:

- 4th Floor, Elevator Lobby
- Outside Room 449
- New bathroom on 1st floor. Test button cannot be found (It may be mounted too high to the ceiling to get to the test button). If that's the case, flip the box so the test button is accessible.

Re-Inspection scheduled to be conducted on or after 09/09/2025 at 09:00

Next inspection scheduled to be conducted on or after 08/19/2026

## Inspection Signatures

### Occupancy Contact Signature

Unable to sign:

Report completed in office.

---

Sasha Santiago  
Security Contact  
708-524-6750  
ssantiago@dom.edu  
7900 Division St.

### Inspector Signature



---

Wiley, Kevin  
--  
Fire Marshal  
630-270-6988  
kwiley@vrf.us